

## **NOTICE TO MARINERS**

Panaji, December 20, 2017

Agrahayana 27, 1939

The Department of Captain of Ports has notified that the Port side (RED) navigation buoy laid west of Old Mandovi Bridge in geographical position Lat 15° 30' 05.6N and Long 73° 49' 57.7 E approximately, has been hit and damaged by unknown vessel. The said buoy no longer exhibits light and only float section is visible at waterline.

Therefore, mariners are required to exercise extreme caution while navigating in the area.

**DI/NB/TSS/PN/GJG/AN/2017/1205**

--

DIRECTORATE OF INFORMATION AND PUBLICITY.  
THIRD FLOOR, UDYOG BHAVAN,  
NEAR AZAD MAIDAN, PANAJI GOA  
PHONE-0832-2422675  
0832-2226047  
0832-2426168  
FAX 0832-2224211