

NOTICE TO MARINERS

Panaji, February 7, 2018
Magha 18, 1939

The Captain of Ports Department has notified that in connection with the blocking of the existing navigational spans of both the Mandovi Bridge for segment erection works of third Mandovi Bridge. All Outbound vessels should navigate the area with minimum speed passing through the port (red) and starboard (green) lighted Buoys keeping the buoys to their Port and Starboard at a safe distance and navigate through spans of new and old Mandovi Bridge.

The owners/masters/serangs of the vessels should strictly and scrupulously adhere to the above instructions and exercise utmost care and utmost caution while approaching/ negotiating the bridges, till further order.